




分圖 No.18



分圖 No.19




分圖 No.20





分圖 No.22





分圖 No. 23





分圖 No. 25





# 橘浦 椿泊浦

40,000

見能林村

堤防欠壞  
現在浸水

2.06

橘町

氣泡噴出區域  
採水處

堤防欠壞(田)  
現在尚浸水

3.63

大原

福井村

3.12

橘尾

橘ヶ浦


椿泊

須屋


平松

3.36


滿生田



分圖 No.28




分圖 No.29




# 喉 穴 佐 那 鞆

$\frac{1}{40,000}$



# 甲 浦

1  
20,000



分圖 No.32

